



SOLID – ATHENS DOUBLE PEDESTAL TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	2	Columns	
Base Box	2	Feet	
Base Box	2	Top Straps	
Table Box	1	Stretcher Foot	

Hardware List and Verification

Quantity	Description	QC Check
16	2" Lag Bolts	
4	Black Lag Bolts	
20	Flat Washers	
6 (threaded into Feet & Stretcher)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION  Do Not Assemble with Power Tools
--

ASSEMBLY INSTRUCTIONS:

- 1) ALIGN THE 4 CENTER HOLES OF EACH TOP STRAP WITH THE 4 PRE-DRILLED HOLES IN EACH COLUMN.
- 2) **LOOSELY** ATTACH THE TOP STRAPS TO ONE END OF EACH COLUMN USING **8 - 2" LAG BOLTS**.
- 3) EACH FOOT HAS TWO PRE-DRILLED HOLES AND A NOTCH WHERE IT WILL ACCEPT THE STRETCHER FOOT. PLACE THE TWO FEET IN THE INTERSECTING NOTCHES ON THE STRETCHER FOOT. ALIGN THE HOLES ON EITHER END OF THE STRETCHER FOOT AND THE PRE-DRILLED HOLES IN THE FEET WITH PRE-DRILLED HOLES IN THE COLUMNS.
- 4) **LOOSELY** ATTACH THE FOOT AND STRETCHER ASSEMBLY TO THE COLUMNS USING THE OTHER **8 - 2" LAG BOLTS**. THIS COMPLETES THE BASE ASSEMBLY.
- 5) TURN THE TABLE TOP UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 6) ALIGN THE OUTERMOST HOLES IN THE TOP STRAPS WITH THE PRE-DRILLED HOLES ON THE BOTTOM OF THE TABLE. ATTACH THEM WITH THE **BLACK LAG BOLTS**. **IMPORTANT: BE CERTAIN TO USE THE BLACK LAG BOLTS, AS THE LONGER 2" LAG BOLTS MAY ACTUALLY GO THROUGH THE TABLE TOP.**
- 7) FINISH TIGHTENING ALL LAG BOLTS INTO PLACE.
- 8) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.

