



## SOLID – FOUR-LEG PEDESTAL TABLE ASSEMBLY

### Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	4	Oval Legs	
Base Box	2	Notched Top Straps	
Base Box	2	Notched Bottom Feet	

### Hardware List and Verification

Quantity	Description	QC Check
16	2" Lag Bolts	
20	Flat Washers	
4	Black Lag Bolts	
4 (threaded into Bottom Feet)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: \_\_\_\_\_

**ATTENTION**  **Do Not Assemble with Power Tools**

### ASSEMBLY INSTRUCTIONS:

- 1) CROSS THE TOP STRAPS TO FORM A “PLUS” SIGN BY INTERSECTING THE NOTCHES TOGETHER.
- 2) USE **8 - 2” LAG BOLTS** TO **LOOSELY** ATTACH EACH OF THE OVAL LEGS TO THE PAIRED OUTER HOLES IN THE TOP STRAPS (IT DOESN’T MATTER WHICH END OF THE LEG). BE SURE THAT THE UNFINISHED SIDE OF THE TOP STRAPS FACES AWAY FROM THE LEGS.
- 3) **LOOSELY** ATTACH THE BOTTOM FEET IN THE SAME MANNER AS STEP 2 USING THE OTHER **8 - 2” LAG BOLTS**. THIS COMPLETES THE BASE ASSEMBLY.
- 4) TURN THE TABLE UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 5) ALIGN THE OUTERMOST HOLES IN THE TOP STRAPS WITH THE PRE-DRILLED HOLES ON THE BOTTOM OF THE TABLE. ATTACH THEM WITH THE **BLACK LAG BOLTS**. **IMPORTANT: BE CERTAIN TO USE THE BLACK LAG BOLTS, AS THE LONGER 2” LAG BOLTS MAY ACTUALLY GO THROUGH THE TABLE TOP.**
- 6) FINISH TIGHTENING ALL LAG BOLTS INTO PLACE.
- 7) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.

