



SOLID – WESTON SPLIT PEDESTAL TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	2	Legs w/ Top Plates	

Hardware List and Verification

Quantity	Description	QC Check
8	Black Lag Bolts	
8	Flat Washers	
4 (threaded into Feet)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION  **Do Not Assemble with Power Tools**

ASSEMBLY INSTRUCTIONS:

- 1) TURN THE TABLE UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 2) ALIGN THE HOLES IN THE TOP PLATES WITH THE PILOT HOLES IN THE BOTTOM OF THE TABLE. FIRMLY ATTACH THE TOP PLATES TO THE TABLE USING THE **BLACK LAG BOLTS**.
- 8) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.

