VERGENNES OCCASIONAL TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	2	Metal Legs	

Hardware List and Verification

Quantity	Description	QC Check
16	1” Lag Bolts	
16	Flat Washers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION Do Not Assemble with Power Tools

ASSEMBLY INSTRUCTIONS:

1) TURN THE TABLE UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.

2) ALIGN THE HOLES IN THE LEGS WITH THE PILOT HOLES IN THE BOTTOM OF THE TABLE. FIRMLY ATTACH THE BASE TO THE TABLE USING THE 1” LAG BOLTS. **NOTE:** THE LEGS MAY NEED TO BE PULLED OUTWARD SLIGHTLY IN ORDER FOR HOLES TO ALIGN.