



DOVER BENCH ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Table Box	2	Legs	
Rail Box	5	Slats	

Hardware List and Verification

Quantity	Description	QC Check
10	Curved Washers	
10	2 1/2" Threaded Studs	
10	Threaded Nuts	
1	Wrench	
10	Finished Veneer Stickers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ASSEMBLY INSTRUCTIONS:

1) ATTACHING SLATS TO LEGS (*FIGURE 1*):

- A. FIRST THREAD STUDS ALL THE WAY INTO SLAT INSERTS, SCREW NUT ON LOOSELY SO FLUSH WITH VERY END.
- B. ALIGN SLATS INTO POSITION LINING THEM UP WITH THE ACCEPTING HOLES IN THE LEG (**HOLES FACE IN**). BE SURE TO ALTERNATE END LENGTHS.
- C. SLIDE 'HALF MOON' SHAPED WASHER IN, WITH CONCAVE FACING NUT. THE PROFILE WILL MATCH MACHINED HOLE.
- D. TIGHTEN WITH PROVIDED WRENCH.

2) COVER ATTACHMENT HOLES IN SKIRT WITH **10 FINISHED VENEER STICKERS**.

3) CAREFULLY TURN BENCH UPRIGHT.





FIGURE 1