



GRAND ISLE BENCH ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	2	Leg Assembly	
Base Box	1	Stretcher	

Hardware List and Verification

Quantity	Description	QC Check
2	2" Lag Bolts	
4	Black Lag Bolts	
6	Flat Washers	
4 (threaded into Bottom Feet)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION  **Do Not Assemble with Power Tools**

ASSEMBLY INSTRUCTIONS:

- 1) ATTACH THE LEG ASSEMBLIES TO THE STRETCHER BY INTERSECTING THE NOTCHES IN AN "I" FORMATION. USE THE 2 - 2" LAG BOLTS TO ATTACH THE PIECES TOGETHER
- 2) TURN THE BENCH TOP UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 3) TURN THE BASE ASSEMBLY UPSIDE DOWN AND ALIGN THE OUTER HOLES OF THE TOP STRAPS WITH THE PRE-DRILLED HOLES ON THE BOTTOM OF THE BENCH TOP.
- 4) ATTACH THE BASE USING THE **BLACK LAG BOLTS**. **IMPORTANT: BE CERTAIN TO USE THE BLACK LAG BOLTS, AS THE LONGER 2" LAG BOLTS MAY ACTUALLY GO THROUGH THE BENCH TOP.**
- 5) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.

