



EXTENSION – NEWFANE TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	2	Legs Assemblies	
Base Box	4	Inner Skirts	

Hardware List and Verification

Quantity	Description	QC Check
12	Black Lag Bolts	
12	Flat Washers	
8	1 5/8" Screws	
12	2 3/4" Screws	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION **Do Not Assemble with Power Tools**

ASSEMBLY INSTRUCTIONS:

- 1) TURN THE TABLE UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 2) WITH THE LEGS POINTING TOWARD THE CORNERS OF THE TABLE TOP (SEE *FIGURE 1*), ALIGN THE HOLES IN THE LEG ASSEMBLIES WITH THE HOLES IN THE BOTTOM OF THE TABLE.
- 3) USE THE **BLACK LAG BOLTS** TO ATTACH THE LEG ASSEMBLY TO THE TABLE TOP (SEE *FIGURE 2*).
- 4) ALIGN THE SCREW HOLES IN THE INNER SKIRTS WITH THE PILOT HOLES IN THE TABLE TOP. USE THE **8 - 1 5/8"** AND THE **12 - 2 1/2"** SCREWS TO ATTACH THE SKIRTS (SEE *FIGURE 3*).
- 5) CAREFULLY TURN TABLE UPRIGHT.




FIGURE 1




FIGURE 2




FIGURE 3

