



EXTENSION – ATHENS SINGLE PEDESTAL TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	1	Column	
Base Box	1 (2)	Top Plate (Top Straps)	
Table Box	2	Curved Feet	

Hardware List and Verification


Quantity	Description	QC Check
12	2" Lag Bolts	
12	Flat Washers	
4 (threaded into Feet)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: _____


ATTENTION  **Do Not Assemble with Power Tools**

ASSEMBLY INSTRUCTIONS:

- 1) IF YOUR TABLE HAS A SQUARE TOP PLATE, PLACE IT WITH THE UNFINISHED SIDE UP ON ONE END OF THE COLUMN. OR IF YOUR TABLE HAS 2 NOTCHED TOP STRAPS, CROSS THEM TO FORM A "PLUS" SIGN BY INTERSECTING THE NOTCHES TOGETHER. SEE DRAWING BELOW.
- 2) ALIGN THE CENTER PRE-DRILLED HOLES IN THE TOP PLATE OR STRAPS WITH THE PRE-DRILLED HOLES IN ONE END OF THE COLUMN. **LOOSELY** ATTACH USING **4 - 2" LAG BOLTS** AND THEN TURN THE ASSEMBLY OVER.
- 3) INTERSECT THE NOTCHES IN THE 2 CURVED FEET.
- 4) ALIGN THE PRE-DRILLED HOLES OF THE CURVED FEET WITH THE PRE-DRILLED HOLES IN THE COLUMN END OPPOSITE THE TOP PLATE OR STRAPS. **LOOSELY** ATTACH USING **4 - 2" LAG BOLTS**. THIS COMPLETES THE BASE ASSEMBLY.
- 5) TURN THE TABLE TOP UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 6) ALIGN THE OUTERMOST HOLES IN THE TOP STRAPS WITH THE PRE-DRILLED HOLES ON THE BOTTOM OF THE EXTENSION SLIDES. ATTACH THEM WITH THE OTHER **4 - 2" LAG BOLTS**.
- 7) FINISH TIGHTENING ALL LAG BOLTS INTO PLACE.
- 8) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.



Base with Top Plate



Base with Top Straps

EXTENSION LEAF/LEAVES SELF STORE NOTES:

EXTENSION TABLES OF THIS TYPE ARE NOT AVAILABLE WITH A SELF STORING LEAF/LEAVES OPTION.