



EXTENSION – NEW TRADITIONS PEDESTAL ROUND TABLE ASSEMBLY

Base Part Location and Verification

Location	Quantity	Description	QC Check
Base Box	1	"X" Shaped Pedestal	
Base Box	2	Notched Top Straps	
Base Box	2	Notched Bottom Feet	

Hardware List and Verification


Quantity	Description	QC Check
8	2" Lag Bolts	
4	3 1/2" Lag Bolts	
12	Flat Washers	
4 (threaded into Bottom Feet)	Levelers	

QUALITY CONTROL CHECK PERFORMED BY: _____

ATTENTION  **Do Not Assemble with Power Tools**

ASSEMBLY INSTRUCTIONS:

- 1) CROSS THE TOP STRAPS TO FORM A "PLUS" SIGN BY INTERSECTING THE NOTCHES TOGETHER.
- 2) ALIGN THE CROSSED TOP STRAPS WITH THE PRE-DRILLED HOLES ON ONE END OF THE "+" SHAPED PEDESTAL (IT DOESN'T MATTER WHICH END). USE **4 - 2" LAG BOLTS** TO **LOOSELY** ATTACH THE TOP STRAPS. BE SURE THAT THE UNFINISHED SIDE OF THE TOP STRAPS FACES AWAY FROM THE PEDESTAL.
- 3) INTERSECT AND **LOOSELY** ATTACH THE NOTCHED BOTTOM FEET WITH THE **4 - 3 1/2" LAG BOLTS**. MAKE SURE THAT THE LEVELERS ON THE BOTTOM FEET ARE FACING AWAY FROM THE PEDESTAL. THIS COMPLETES THE BASE ASSEMBLY.
- 4) TURN THE TABLE UPSIDE DOWN AND PLACE ON A SOFT, NON-ABRASIVE SURFACE.
- 5) ALIGN THE OUTERMOST HOLES IN THE TOP STRAPS WITH THE PRE-DRILLED HOLES ON THE BOTTOM OF THE EXTENSION SLIDES. ATTACH THEM WITH THE OTHER **4 - 2" LAG BOLTS**.
- 6) FINISH TIGHTENING ALL LAG BOLTS INTO PLACE.
- 7) CAREFULLY TURN TABLE UPRIGHT. ADJUST LEVELERS AS NEEDED.



EXTENSION LEAF/LEAVES SELF STORE NOTES:

EXTENSION TABLES OF THIS TYPE ARE NOT AVAILABLE WITH A SELF STORING LEAF/LEAVES OPTION.